



LEARNING FROM INCIDENTS

INVESTIGATION REPORT

MORANBAH NORTH MINE

Metallurgical Coal

Incident Number: IN.00205770

Classification: *DNRME HPI*

Incident Title: Methane exceedance in TG of LW604

Incident Date: 20.07.2019

Report Date: 20.07.2019

CONFIDENTIAL

Learning from Incidents Investigation Report

1	Executive Summary	3
2	Investigation Team Members	3
3	Key Witnesses	4
4	Methodology and Tools Used	4
5	Incident Report Summary	5
6	Incident Data Collection	6
7	Contributing Factors / Causes	6
8	Critical Control Failure	7
9	Findings / conclusions	7
10	Preventative actions / Recommendations	8
11	Test for Effectiveness	8
12	Investigation Report Sign –Off	9
13	Analysis Tool Appendices	10
14	Time Series Event Chart	10
15	Change Analysis	10
16	Why Analysis	11
17	Supporting Evidence Appendices	12
18	Initial Incident Report	12
19	Statements	14
20	Diagrams/Maps	22
21	Investigation Report assistance	24
22	Record of Amendments	24

1 EXECUTIVE SUMMARY

Power to LW604 face tripped back to the DCB at 11:50am on the 20th of July while completing the 2nd run into the TG. During the initial investigation the face ERZ Controller identified methane (CH₄) blowers in the floor between #105 and #110 PRS and a GB CH₄ concentration up to 2.3%. Further investigation found the TG drive CH₄ sensor had failed and there was >2.5% CH₄ in the TG roadway.

Leading up to the time of the event CH₄ level in the TG roadway was between 1.6% and 2%. At 12:12pm the TG outbye sensor passed 2.5% CH₄, peaking at 12:22pm at a GB concentration of 3.36% CH₄ and did not drop below 2.5% until 1:25pm. SO670A was the closest goaf drainage well but was in standby mode due to low methane and high oxygen (O₂).

The face ERZ Controller used cool tubes and brattice sails along the face to direct ventilation into the rear walkway and dilute CH₄ make from #105 PRS to the TG. The TG drive, TG CMU, and the shearer were checked internally for gas, and the incident site was then cleared by the Undermanager in consultation with the Underground Mine Manager. Production then recommenced at 5:30pm.

2 INVESTIGATION TEAM MEMBERS

List of team members			
Name	Position Title	Designation	Qualifications
Kelvin Sloan	LW coordinator	Investigation Lead	S123, G2, Trade Cert
Tim Johnson	HSE coordinator	Facilitator	S123, G2, Dip
Scott Fraser	ERZ controller	ERZ Controller	S123, G2, Cert 4 U/G operations
Sam Watson	Geologist	Team member	S123, G2, Geology Batch
Hamish Rowland	Drilling supervisor	Team member	S123, G2
Ben Roberts	Mine Technician	Team member	
Tim Miller	Mine Technician	Team member	
Jamle Gibson	Shift Undermanager	Team member	S123, G2, Cert 4 U/G operations
James Grebert	Ventilation officer	Team member	S123, G2, VO
Colin Standley	Mine Technician	Team member	

3 KEY WITNESSES

List of Key Witnesses		
Name	Position Title	Statement
Tim Miller	Mine Technician	Yes
Scott Fraser	ERZ Controller	Yes
Grant Dixon	Mine Technician	Yes
Jamie Huff	Mine Technician	Yes

4 METHODOLOGY AND TOOLS USED

An investigation has been conducted in accordance with the Anglo American investigation methodology known as the Learning from Incidents model, supported by various investigative tools.

The analysis tools used for this investigation are:

Analysis Tool	Tools completed within this report - Yes/No
Time Series Events Chart	Yes – mandatory tool
Control Analysis	No
Human Behaviour Analysis	No
Change Analysis	Yes
Why Analysis	Yes

Supporting evidence	Attached as Appendix if applicable - Yes/No
Initial Incident Report	Yes – mandatory evidence
Relevant SHMS Documents	Yes
Photographs	No
Statements	Yes
Diagrams / Maps / Physical Evidence	Yes

UNCONTROLLED WHEN PRINTED

4 of 24

Print Date: 8/29/2019 12:47 PM

Met Coal_11-9

Incident Investigation Report

Version 2

Revision

Date 09 May 2019

Date 09/05/2024

5 INCIDENT REPORT SUMMARY

Summary of Incident						
Incident Number	IN.00205770	Department	Longwall			
Area / location	LW604 TG roadway	Company (Anglo/Contractor)	Anglo			
Summary of findings from Incident Investigation						
Incident Category	Agent	Actual ISR Rating	Potential ISR Rating	Date of Incident	Time of Incident	Number of hours worked
Legal	CH ₄ exceedance	Minor	Moderate	20/7/19	11:50am	3hrs
Task being performed at time of incident	Production				Planned or Unplanned task?	
					Unplanned	Planned
Summary of incident	Shearer cutting back into TG to complete second run of the shuffle cut. Once shearer reached #141 PRS face power tripped back to DCB.					
Immediate actions taken	Removed operators back to the MG and investigation power trip. Upon investigation found CH ₄ blowers in the rear of PRS between #105 and #110 with GB CH ₄ up to 2.3% in rear walkway at #110 PRS and PGD was reading >2.5%. Further investigation found >2.5% CH ₄ in TG roadway.					

UNCONTROLLED WHEN PRINTED

5 of 24

Print Date: 8/29/2019 12:47 PM

6 INCIDENT DATA COLLECTION

PEEPO	Facts/Observations
People	<ul style="list-style-type: none"> Five CMW on the face at the time of the event ERZC present
Equipment	<ul style="list-style-type: none"> Shearer TG drive Personal gas detector Static gas monitors Goaf wells
Environment	<ul style="list-style-type: none"> Goaf TG roadway Shearer at #141 chock Adjacent goaf present Close proximity of the GML seam (0.2 to 0.3 meters) GP1, PTUFF, GP0 within six meters of the GM seam roof (7.5 meters from the cut roof) Floor heave Goaf well SO670A on standby due to low methane content until after the goaf event
Procedures	<ul style="list-style-type: none"> Goaf drainage TARP Gas Management TARP Operational TARP Goaf Drainage Management Plan Longwall portion of degassing and purging procedure
Organisation	<ul style="list-style-type: none"> Rates of retreat vs gas drainage capabilities

7 CONTRIBUTING FACTORS / CAUSES

Possible Causational Factors		
Factor	Describe Cause	Applicable
Organisational	<ul style="list-style-type: none"> Rates of retreat vs gas drainage capabilities 	Yes
Task/environment Conditions	<ul style="list-style-type: none"> Goaf Adjacent goaf present Close proximity of the GML seam (0.2 to 0.3 meters) GP1, PTUFF, GP0 within 6m of the GM seam roof (7.5m from the cut roof) Floor heave 	Yes
Individual/team actions		No
Absent/failed defences	<ul style="list-style-type: none"> Goaf well SO670A on standby due to low methane content until after the goaf event 	Yes

Met Coal_11-9

Incident Investigation Report

Version 2

Revision

Date 09 May 2019

Date 09/05/2024

8 CRITICAL CONTROL FAILURE

(List any identified critical control failures that contributed to the event. Liaise with the relevant department superintendent or critical control owner to establish if this section is applicable.)

CC Failure Identification	
Did any critical controls fail?	No
What / which critical controls failed? (List CT number)	
Why did the critical control fail?	
How did the critical control fail?	
What additional or revised critical controls and/or monitoring activities need to be established/change to mitigate risk of recurrences, or to improve risk control?	

9 FINDINGS / CONCLUSIONS

- Prior to the incident the TG roadway CH₄ had been sitting between 1.6 and 2% GB.
- Prior to the incident a total of 5 goaf drainage holes online.
- SO670A was in standby mode due to low CH₄ and high O₂.
- Close proximity of the GML seam (0.2 - 0.3m)
- At 12:12pm the TG outbye sensor passed 2.5% CH₄ peaking at 12:22pm at a GB concentration of 3.36% CH₄ and did not drop below 2.5% until 1:25pm.
- 72m³ ventilation across face at time of incident.

UNCONTROLLED WHEN PRINTED

7 of 24

Print Date: 8/29/2019 12:47 PM

Met Coal_11-9 Incident Investigation Report

10 PREVENTATIVE ACTIONS / RECOMMENDATIONS

The following key actions were identified to prevent recurrence and have been assigned as detailed below in Enablon.

Task Description	Hierarchy of Control	Task Assignee	Due Date	Task ID
Revise the UIS strategy in similar areas to ensure adequate drainage of the GML	Admin	Kevin Doyle	15/9/2019	TS.01096536
Revise the degassing and purging procedure to ensure specific to longwall operations	Admin	Luke Hamilton	15/9/2019	TS.01096537
Review geotechnical goaf caving around TG 604 with adjacent goaf	Admin	Charles Sweeney	15/9/2019	TS.01096538
Review GML gas content to ensure drainage strategy is effective	Admin	Ken Blades	30/10/2020	TS.01096539

11 TEST FOR EFFECTIVENESS

Post Implementation Action Plan

Test of effectiveness is to be done to ensure that the above actions to prevent recurrence have worked as intended. (Nominally scheduled 3,6 or 12 months after completion of preventative action plan)

Enablon Task No.	Action Description	Responsible Person	Due Date	Completed Date
TS.01096540	Review actions from completed LFI to ensure all actions have been completed and are effective.	Wesley Noble	30/11/2020	

Met Coal_11-9

Incident Investigation Report

Version 2

Date 09 May 2019

Revision

Date 09/05/2024

12 INVESTIGATION REPORT SIGN -OFF

The Incident Investigation Team submits this report as a true reflection of the information gathered. To maximize the preventive potential of the investigation report, the findings, conclusions and learning's of the report should be distributed as appropriate.

<i>Department Manager</i>		
Wesley Noble	Signature	Date
	Confidential	30-8-19
<i>SHE Manager</i>		
Chris Moger	Signature	Date
	Confidential	30/8/19.
<i>General Manager</i>		
Scott Dobbie	Signature	Date
	Confidential	30/8/19
<i>Head of Operations</i>		
Paul Stephan	Signature	Date
<i>Additional EXCO member signoff – if applicable</i>		
Michael Lerch	Signature	Date
	Confidential	30/8/19.

Confidential

G. Britton

24/09/19.

UNCONTROLLED WHEN PRINTED

13 ANALYSIS TOOL APPENDICES


14 TIME SERIES EVENT CHART

Time	Event or Condition
20/7/19	
9:00am-10:00am	Completed start of shift briefing and travelled into LW604.
10:00am-11:50am	Production as planned.
11:50am	Lost face power due to CH ₄ trip.
1:00pm-5:00pm	Setup brattice wings and sails onface to manage CH ₄ . Degassed Shearer, TG CMU and TG drive motors.
5:00pm-5.30pm	Crew waiting for approval to start production.
5:30pm	Commenced production.

15 CHANGE ANALYSIS

Change Analysis			
Normal Practice	Situation or practice at the time of the incident	Gap (difference)	Impact of Difference
Goaf drainage well operating	Well SO670A in standby mode due to low methane and high O ₂	Can't pull gas from the TG goaf area, closest to the face	With closest goaf well on standby will result in less control of the gas content in the TG roadway
Methane content in TG generally between 1.2% and 2%	Leading up to the time of the event CH ₄ level was between 1.6% and 2%. Shearer speeds whilst coming into the TG was being halted to assist with reducing CH ₄ levels.	Modified operation of the shearer with consideration of the methane content	Gas management to prevent exceedance

16 WHY ANALYSIS



17 SUPPORTING EVIDENCE APPENDICES
18 INITIAL INCIDENT REPORT

Enablon ID No.

Hazard & Incident Report Form



To be completed by reporting person with assistance from Supervisor (Surface incidents) or ERZ Controller (UG incidents). ALL Sections of this form are mandatory unless marked.

Title of Hazard / Incident: 72.5% METHANE AT TA DRIVE & INS LIGHT TA ROADWAY.
Date occurred: 20/7/19 **Time:** 1150

Classification: Hazard Safety Material Losses / Damage / Business Interruption Legal / Regulatory
 Environment Social / Community Impact on Reputation Health Illness Workplace Exposure

Department: Outbye Development Longwall Compliance Tech Services Seampas SHE
 Business Improvement Human Resources Commercial / Supply Chain Maintenance / Engineering Other

Specific Location: LIGHT TA ROADWAY & TA DRIVE

Reported By: Include ID# S. SPANER 605120

Key Person(s) Involved: Include ID# TIM MILLER, JAMES HUFF & SCOTT FROBER.

Others Involved: Include ID# (e.g. Witnesses) AS ABOVE.

Equipment Involved: TA DRIVE, SHERMAN. **ERZC / Supervisor:** Include ID# S. SPANER 605120

Crew: C **Contractor Group:** LOZANELL

Shift Length: 12 HRS **Hours into Shift:** 3 HRS **Consecutive days worked:** 1

Incident Description: THE TA ROADWAY HAD JUST BEEN CUT OUT ON ITS FIRST RUN, THE SHERMAN CUT BACK TO #129 CHECK & THIS CUTTING INTO THE TA FOR ITS SECOND (SNAKE) & AT #114 POWER WAS LOST TO THE FACE BACK TO THE DUB.

Diagram: (Attach additional notes if required)

Immediate Direct Cause: METHANE. **Mechanism:** FACE OF METHANE.

Immediate Corrective Actions Taken: RETURN OPERATORS BACK TO THE M9, INVESTIGATED TRIP. WENT INVESTIGATION FOUND CH4 BLOWERS IN REAR OF CHECK BETWEEN #105 & #110 WITH GAS CUT UP TO 2.3% INS REAR WALKWAY AT #110, FOUND TA DRIVE SENSOR HAD FRIED OVER & PDS WAS READING 72.5% CH4 NEXT TO SENSOR. FURTHER INVESTIGATION FOUND 72.5% CH4 IN TA ROADWAY.

Refer to attached Moranbah North Risk Matrix for below:

Actual Consequence: Not Applicable for Hazards	Insignificant <small>(Total Mtd Loss, damage < 0.01% annual revenue etc.)</small>	Minor <small>(Medical treatment, damage < 0.1 - 0.1% annual revenue)</small>	Moderate <small>(Lost time injury, damage 0.1 - 1.0% annual revenue)</small>	High <small>(Permanent disability, fatality, Anglo HPI)</small>	Major <small>(Permanent permanent disability, fatality, Anglo HPI)</small>
Potential Consequence:	Insignificant <small>(Total Mtd Loss, damage < 0.01% annual revenue etc.)</small>	Minor <small>(Medical treatment, damage < 0.1 - 0.1% annual revenue)</small>	Moderate <small>(Lost time injury, damage 0.1 - 1.0% annual revenue)</small>	High <small>(Permanent disability, fatality, Anglo HPI)</small>	Major <small>(Permanent permanent disability, fatality, Anglo HPI)</small>
Has the hazard, defect or incident been effectively controlled on shift? If not, why not?				YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>

MN1470 NB Print

UNCONTROLLED WHEN PRINTED



Met Coal_11-9 Incident Investigation Report

Hazard & Incident Report Form



People's Behaviours:	Timeline	
<u>N/A</u>	0900-1000	START OF SHIFT & TRAVEL TO LHM.
	1000-1100	CHANGING TO WORK & MAINTAIN TA (2 SHEETS)
Environment:	1100-1200	POWER LOST ON FACE - INVESTIGATED.
HIGH CHY IN SEAM BELOW. COAT HOLE NOT YET AS	1300-1400	DECREASED SHEETS FROM 2 TO 1 - SELF SERVICE WINGS & SIZES TO REMOVE CHY ON FACE.
Equipment:	1500-1700	WAITING ON REPORT TO START UP
TA DRIVE CHECKED.	1800-2000	Production.
	2000-2100	TRAVEL OUT.
Procedures:		
DE-CASSING PROCEDURE FOLLOWED.		

Additional Actions to prevent recurrence: (ERZ Controller/ Supervisor to complete)

Action Description	By Whom	Action Due (date)	Enablon ID #
INVESTIGATE UG DAMAGE OFFICE FOR LOWER SEAMS.	K. SLATS.	20/8/19.	
INVESTIGATE COAT HOLE SEAMS ARE NOBUILT.	K. SLATS.	20/8/19.	

Is a Banner Alert req. lred to be issued? Yes No
 If yes, which Banner Alert: Green Orange Red X

Incident Sign Off: (TO BE SIGNED OFF AND RETURNED TO SAFETY OF PARTMENT W ITHIN 24HRS OF INCIDENT)

Person Reporting	Date: 20/7/19.	Supervisor (for Surface Incidents) ERZ Controller (for UG Incidents)	Date: 20/7/19
Name: S. FRAGER	Signature: Confidential	Name: SPANGLER	Signature: Confidential
Undermanager	Name: JAMIE GIBSON	Signature: Confidential	Date: 21/7/19.
Superintendent / Manager	Name:	Signature:	Date: / /
Entered into Enablon by (Name):			Date: / /



Met Coal_11-9 Incident Investigation Report

19 STATEMENTS

Statement – Tim Miller

Document No.	MM HS0001.10 FRM	Revision No	2	Issue Date	31/12/14
Print Date	31/12/2014	Authorised by	S Garrivan, HSE Manager Rep		



AngloAmerican Anglo American Metallurgical Coal – Morumbah North
 Operations PO Box 17 Tel (07) 49688 00
 Morumbah Old 4744 Fax (07) 49688 20
 Old 4744 Int 1 81 749 88 600

Incident Investigation Initial Witness Statement Form

Name:	Tim Miller	Job Title:	Mine tech
Telephone No.:	Confidential	Supervisor:	S Fraser
Interviewer: Title/Position:		Date/Time:	21-7-19
Work Location:	604 Longwall		
Location of Incident:	chock 140		
Incident Time and Date:	20-7-19 11-50AM		
Please describe fully everything that you saw and heard before, during and after the incident (use additional paper as needed):			
was cutting from 129chock towards tailgate, shearer stopped tramming on gas when gas subsided was told to keep tramming from maingate operator, moved two or three chocks and power went down on high gas.			
Please describe all that you know about the work and conditions leading up to the incident (use additional paper as needed):			
gas was decreasing when i was told to keep tramming			
Note anything unusual you observed before or during the incident (sights, sounds, odours, etc.):			

File Ref

[http://eamcmorp.anglo.local/sites/SHE-MS/Lists/SHE/Documents/ViewOnly/FRM_Forms/MMM_HS0001.10_FRM_Incident Investigation Initial Witness Statement Form.docx](http://eamcmorp.anglo.local/sites/SHE-MS/Lists/SHE/Documents/ViewOnly/FRM_Forms/MMM_HS0001.10_FRM_Incident%20Investigation%20Initial%20Witness%20Statement%20Form.docx)

Page 1 of 2



UNCONTROLLED WHEN PRINTED

Print Date: 29/08/2019 12:47 PM

CONFIDENTIAL

Met Coal_11-9 Incident Investigation Report

Document No.	50026.10	Revision No.	2	Issue Date	31/12/14
Print Date	31/12/2014	Authorised by	S Garvan / HSE Manager Rep		

What conditions influenced the incident (weather, time of day, equipment malfunctions, etc)??

How could the incident have been prevented?

Please list other possible witnesses:

Additional comments/observations:

Signature: _____ Date/Time: _____



UNCONTROLLED WHEN PRINTED

15 of 24
 Print Date: 29/08/2019 12:47 PM

CONFIDENTIAL

Met Coal_11-9 Incident Investigation Report

Statement – Scott Fraser

Met Coal_11-9 Incident Investigation Report

Document No.	MAM_H50001.10 FRM	Revision No	2	Issue Date	31/12/14
Print Date	31/12/2014	Authorised by	S Ginnivan / HSE Manager Rep		



AngloAmerican Anglo American Metallurgical Coal Moranbah North
 Operations P ox 172 Tel (07) 49688 6 0
 Moranbah Old 4744 Fax (07) 49688 6 0
 Moranbah Old 4744 Int'l + 61 749 68 600

Incident Investigation Initial Witness Statement Form

Name:	SCOTT FRANKS	Job Title:	DEPUTY
Telephone No.	Confidential	Supervisor:	J. GIBSON
Interviewer:	NA.	Date/Time:	20/7/14.
Title/Position			
Work Location:	LW604		
Location of Incident:	LW604 FACE.		
Incident Time and Date:	12:00PM 20/7/14.		

Please describe fully everything that you saw and heard before, during and after the incident (use additional paper as needed):
 I CARRIED OUT MY FIRST INSPECTION OF THE FACE WITH NO ISSUES OR CHANGES OF CONCERN, I NOTICED THE TG DRIVE SENSOR WAS 0.6% CH4 ON FIRST INSPECTION, MID FACE 0.2% & 0.5% @ #110. THE SHERDER HAD CUT POWER IN TG, I MADE MY WAY BACK TO TG & AT #110 POWER WAS LOST TO FACE. I REMOVED PERSONS FROM FACE TO TG & INVESTIGATED. AT #100 I NOTICED THE TG CH4 IN REAR WALKWAY WAS > 1% & FOUND CH4 BLENDING IN BECK OF WALKWAY WITH MAX 2.3% CH4 IN REAR WALKWAY AT #110. I INSPECTED TG DRIVE SENSOR & FOUND 2.5% CH4 AT SENSOR 15 MINUTES AFTER POWER WAS LOST. I CONTACTED UNDETFANDED

Please describe all that you know about the work and conditions leading up to the incident (use additional paper as needed):
 I PROVIDED UPDATE OF WHAT I FOUND. SHERDER STOPPED AT #111. WE THEN CONTACTED EEM & WAS TOLD TO DE-CASS SHERDER, TG CH4 & TG DRIVE. LUCKYS STARTED HV SUCKING PROCESS FOR DE-CASSING. WE EXPECTED 2X WINGS TO VENTILATE REAR WALKWAY @ 95 & 100 CHECKS WE

Note anything unusual you observed before or during the incident (sights, sounds, odours etc)
 MOVED THE COOL TUBES TO FACE ROOF OF CHOCKS IN REAR WALKWAY TO DILUTE & DISTRIBUTE LAYERING. WE DE-CASSED ELECTRICAL ENCLOSURES AS MENTIONED ABOVE & CHANGED OUT TG DRIVE SENSOR. SENSOR WAS STILL READING UP & DOWN SO OPENED FLAPS IN TG CH4 & PUT WING UP TO FLUSH CH4 OUT UNDER LAYERING WITH VENTILATION. SENSOR STABILISED. ERECTED BATTERY BARRIERS REAR OF CHOCKS FROM #100-#120 TO BLOCK CH4 FROM ENTERING WALKWAY. GOT APPROX TO STREET AGAIN CUT 1.5 SHEARS WITH NO ISSUES.



UNCONTROLLED WHEN PRINTED

17 of 24
 Print Date: 29/08/2019 12:47 PM

CONFIDENTIAL

Met Coal_11-9 Incident Investigation Report

Document No.	50026.10	Revision No.	2	Issue Date	31/12/14
Print Date	31/12/2014	Authorised by	S Ginnivan / HSE Manager Rep		

What conditions influenced the incident (weather, time of day, equipment malfunctions, etc.)?

IT WAS BETWEEN DRIVING HIGH & LOW

How could the incident have been prevented?

INCREASED USE & WORK DRAINAGE.
 WAS NOT CAUTION ISSUED BEFORE SO SLAMMING
 DOWN INTO TR WAS NOT CONSIDERED

Please list other possible witnesses:

J. HUFF, T. MILLER.

Additional comments/observations:

AS PER FRONT PAGE

Signature: Confidential Date/Time: 20/1/19.



UNCONTROLLED WHEN PRINTED

18 of 24
 Print Date: 29/08/2019 12:47 PM

CONFIDENTIAL

Met Coal_11-9 Incident Investigation Report

Statement – J Huff



Incident Investigation Initial Witness Statement Form

Name:	J HUFF	Job Title:	OPERATOR
Telephone No.:		Supervisor:	
Interviewer: Title/Position:		Date/Time:	21/7/11
Work Location:	MG 604		
Location of Incident:	LONGWALL FACE TAILGATE		
Incident Time and Date:	20/7/19 11-50 AM		
Please describe fully everything that you saw and heard before, during and after the incident (use additional paper as needed):			
WHILE STANDING AT 115 CLOCK WAITING FOR THE SHARPER TO GO IN AND OUT OF T/GATE TALKING TO BLAKE TO SWAP OUT, THE LIGHTS WENT OUT, THEN TOLD TO PROCEED TO THE MAINGATE.			
Please describe all that you know about the work and conditions leading up to the incident (use additional paper as needed):			
HORIZON OK DUSTY AS USUAL			
Note anything unusual you observed before or during the incident (sights, sounds, odours, etc.):			
NOTHING OUT OF THE ORDINARY			



UNCONTROLLED WHEN PRINTED

19 of 24
Print Date: 29/08/2019 12:47 PM

CONFIDENTIAL

Met Coal_11-9 Incident Investigation Report

Primary information gathered during initial investigation.

Primary Information

- **Precise location of the accident/incident.**
 - Longwall 604 Maingate Chainage.2398m
- **When the accident/incident happened**
 - 20/07/2019 1200 hrs
- **Number of persons involved with the incident**
 - Nil – HPI gas exceedance.
 - TG 604 B Heading 1 c/t > 2.5 % @ 1212 Hrs
 - TG 604 B Heading 1 c/t = 3.36 % @ 1222Hrs
 - TG 604 B Heading 1 c/t < 2.5 % @ 1325Hrs
- **4.Name of person who was injured from the incident.** Nil
- **Name of any person who saw or was present when the incident happened.**
 - Longwall C Crew Shearer Op Tim Millar ,, Chock Jamie Huff. ERZC Scott Fraser.
- **6.A brief description of the accident/incident**
 - Shearer was docking at the tailgate drive. Goaf flushed in forcing methane over the tailgate drive Sensor which tripped power to the face . Methane levels reached outbye as above , Ventilation Dept will trend Sensors.
 - EEM UMM notified, Degassing as per SWG 52315
 - Incident Report and witness Statements being prepared.

See Attached Control Room Timeline.

Timeline of events gathered by CRO

Sullivan, Mick

From: O'Hara, Glenn
Sent: Saturday, 20 July 2019 1:46 PM
To: Lerch, Michael; Sullivan, Mick; Gibson, Jamie; Taft, Patrick; Dobbie, Scott; Bruce, David; Grebert, James; Sloan, Kelvin; Kelly, Brendan
Subject: Timeline LW CH4 HPI Sat 20 Jul 19

The below is the time line from control

1144 Shearer In TG
 1152 K Sloan: ask Seamgas to see if they can increase CH4 suction
 1159 CH4 on face TG drive rising
 1159 CH4 sharply rises to over 3% and sensor falls and goes into negative reading, U/M V/O notified
 1205 TG inby sensor rising to over 3% max reading 3.29% at 1208
 1210 SO670A turned up to draw 300l/s
 1217 TG O/B sensor rises to over 3% max reading 3.40% at 1218
 1230 S Fraser #97 >1% rear walkway, #99 > 1% walkway, #108 GB 2.3%, TG off scale
 1231 Audible blower rear #109
 1230 SO670A flow from 305 l/s to 1219 l/s
 1234 Contacted M Lerch, Plan in place to brattice chocks to flush rear of chocks, called S Dobbie, P Taite, B Kelly, D Bruce
 1327 K Sloan booking out Brattice, Gas detectors, probe, venturi, etc.
 1343 Time of email TG inby 2.09% CH4 O/B 2.38% CH4

21 of 24



UNCONTROLLED WHEN PRINTED

Print Date: 29/08/2019 12:47 PM

CONFIDENTIAL


Met Coal_11-9 Incident Investigation Report

20 DIAGRAMS/MAPS

1. Shearer @ #140 shield - start to rise CH₄ at TG Inbye sensor




1. Max CH₄ - TG inbye sensor



Met Coal_11-9 Incident Investigation Report

1. Max CH₄ - TG outbye sensor



21 INVESTIGATION REPORT ASSISTANCE

- 1) [Anglo American Risk Matrix](#)
- 2) [Anglo American Incident Agents List](#)
- 3) [Anglo American Hierarchy of Controls](#)
- 4) [DNRM Causational Factors Examples](#)

22 RECORD OF AMENDMENTS

Issue 7	:	Site adaptation to Moranbah North Mine requirements and guidelines.	06 January 2019, Chris Moger, Timothy Johnson
Issue 6	:	Full review to align the investigation report to the Learning from Incidents process being rolled out at Met Coal in 2018.	08 June 2018, Chris Gately, Lynda Butler
Issue 5	:	<ul style="list-style-type: none"> • Sign off table updated to include "Additional EXCO" member signoff. • Section 7 – New – Critical Control Failure (for HPI's only) • References to Met Coal removed. 	15 September 2015, Allan Gordon
Issue 4	:	Reviewed Sign off table updated to include sign off from Head of Operations	22 April 2014, Allan Gordon
Issue 3	:	Reviewed for currency – reformatted	8 January 2014, Bruce Gavin
Issue 2	:	Reviewed to align with Enablon Incident Database	6 March 2013, Graeme Redding
Issue 1	:	New Template	15 December 2011, Bruce Gavin