



# LEARNING FROM INCIDENTS

## INVESTIGATION REPORT

### GRASSTREE MINE

#### Metallurgical Coal

**Incident Number: IN.0211887**

**Classification: High Potential Incident**

**Incident Title: CH<sub>4</sub> concentration >2.5% in TG808**

**Incident Date: 25/10/2019**

**Report Date: 05/12/2019**

Met Coal\_11-9

Incident Investigation Report

Version

Date

## Learning from Incidents Investigation Report

1	Executive Summary	3
2	Investigation Team Members	3
3	Key Witnesses	3
4	Methodology and Tools Used	3
5	Executive Summary of Incident	4
6	Description of Incident	4
7	Critical Control Failure	5
8	Findings / conclusions	6
9	Preventative actions / Recommendations	6
10	Test for Effectiveness	6
11	Investigation Report Sign –Off	6
12	Evidence & Analysis Tool Appendice	7
13	Record of Amendments	13

Met Coal\_11-9

Incident Investigation Report

Version

Date

## 1 EXECUTIVE SUMMARY

While in production the 808TG roadway sensor detected > 1.9% CH<sub>4</sub> and latched the shearer. The ERZ Controller decided to do a tailgate inspection while the longwall was down and detected 2.56% CH<sub>4</sub> in the tailgate roadway between the face and 19ct.

It appears that this was the result of the tailgate ventilation not being set up in the way the system was designed.

## 2 INVESTIGATION TEAM MEMBERS

Graeme Read - ERZC

Danny Brouwer – Technical Services Superintendent

## 3 KEY WITNESSES

List of Key Witnesses	
Name	Designation
Andrew Firle	Mining Senior Official
Graeme Read	ERZ Controller

## 4 METHODOLOGY AND TOOLS USED

An investigation has been conducted in accordance with the Anglo American investigation methodology known as the Learning from Incidents model, supported by various investigative and analytical tools.

The analysis tools used for this investigation are:

Analysis Tool	Attached as Appendix if applicable - Yes/No
Time Series Events Chart	Yes – mandatory tool
Control Analysis	Yes / No
Behaviour Analysis	Yes / No
Change Analysis	Yes / No
Why Analysis	Yes / No

Met Coal\_11-9

## Incident Investigation Report

Version

Date

## 5 EXECUTIVE SUMMARY OF INCIDENT

Summary of Incident						
Incident Number	211887		Department	Technical Services		
Area / location	LW808 195 chock to tailgate		Contracting Company (if applicable)			
Summary of findings from Incident Investigation						
Incident Category e.g. Safety, Health, Env, Legal, Reputation, Community.	Agent EG – Fall of Ground	Actual ISR Rating	Potential ISR Rating	Date of Incident	Time of Incident	Number of hours worked
Legal and Regulatory	Non compliance	Minor	Minor	25/10/19	18:35	8
Task being performed at time of incident	LW808 Tailgate inspection				Planned or Unplanned task?	
					Unplanned	Planned
Summary of Incident	Whilst cutting out the Maingate the LW808 tailgate gas exceeded 1.9% in the roadway and therefore latched the shearer. The ERZ Controller decided to do a tailgate inspection and found > 2.5% CH <sub>4</sub> . A maximum of 2.56% CH <sub>4</sub> was detected in the tailgate roadway between 195 chock and 19ct.					
Immediate actions taken	Reported to MSO and waited for gas to reside.					

## 6 DESCRIPTION OF INCIDENT

The Longwall tailgate ventilation set up is designed in such a way that a small portion (3-5 m<sup>3</sup>/s) of the air from the longwall face flows inbye the tailgate to the next pillar and crosses at the next cut through into C hdg.

This allows for the additional air dilution that comes into A hdg at the last open cut through to be utilized to fully dilute the TG gas levels and run the last section of the TG to the most inbye open cut through on LW face return air quantity with lower gas levels.

This system was effectively utilized in previous three heading gate roads but had not been utilized in the last two longwall blocks. It has been reintroduced for LW808 due to the two-heading tailgate layout without an adjacent block.

The system relies on the limited resistance applied by brattice stoppings and therefore allowing low air quantities to flow through these areas (see attached schematic).

## Met Coal\_11-9

## Incident Investigation Report

Version

Date

Because the majority of the gas would report to C hdg in this system, the CH<sub>4</sub> sensor to monitor the longwall return is placed in C hdg to accurately monitor the return gas levels as the A hdg roadway in the last open cut through would contain lower gas levels.

On the start-up of the longwall block the 20ct stopping was left in place, which became the stopping just inbye the longwall as soon as the longwall went past it. This means that the resistance in this cut through was much higher compared to a brattice stopping and therefore did not allow for sufficient air to migrate through the inbye cut through.

The stopping at 21-22ct A hdg was replaced by brattice, but being further inbye must have been too far away to provide for sufficient airflow.

Since the system on startup did not provide for sufficient airflow through goaf inbye the tailgate, all gas reported to the A hdg roadway inbye the last open cut through. This air is diluted at the last open cut through and therefore the roadway sensor would have been reading a lower CH<sub>4</sub> value than the concentrations in the A hdg roadway.

At the time of the incident the roadway sensor was reading just over 1.9% but 2.56% CH<sub>4</sub> was recorded in the TG return.

The problem was immediately solved by running a brattice wing inbye the last open cut through from the A hdg roadway to the longwall tailgate. This allow for additional air to be pushed up the tailgate roadway to provide adequate dilution.

Since then brattice stoppings have been installed in the cut throughs and the problem has no longer occurred.

## 7 CRITICAL CONTROL FAILURE

(List any identified critical control failures that contributed to this event)

What / which critical controls failed? (List CT number)	
Why did the critical control fail?	
How did the critical control fail?	
What additional or revised critical controls and/or monitoring activities need to be established/change to mitigate risk of recurrences, or to improve risk control?	

Met Coal\_11-9

## Incident Investigation Report

Version

Date

## 8 FINDINGS / CONCLUSIONS

The start up of Longwall 808 did not have the tailgate ventilation set up adequately to allow for 3-5 m3/s to migrate inbye the longwall face to go across the inbye cut through and therefore keep the majority of the tailgate gas away from the A hdg Tailgate return between the LW face and the most inbye open cut through.

The Tailgate CH<sub>4</sub> sensor is located in C hdg. Because of the above inadequacy, the majority of the gas was coming out of the A hdg return and being diluted in the last open cut through, the CH<sub>4</sub> sensor did not adequately measure the tailgate gas concentration. This allowed for Tailgate gas levels to be higher than the levels recorded in C hdg.

## 9 PREVENTATIVE ACTIONS / RECOMMENDATIONS

The following key actions were identified to prevent recurrence and have been assigned as detailed below in Enablon.

Task Description	Hierarchy of Control	Task Assignee	Due Date	Task ID
N/A – This situation cannot occur at Grasstree anymore as there will be no more three heading tailgates or new blocks in fresh areas with two headings in the tailgate.				

## 10 TEST FOR EFFECTIVENESS

### Post Implementation Action Plan

Test of effectiveness is to be done to ensure that the above actions to prevent recurrence have worked as intended. (Nominally scheduled 3,6 or 12 months after completion of preventative action plan)

Enablon Task No.	Action Description	Responsible Person	Due Date	Completed Date
	N/A – This situation cannot occur at Grasstree anymore as there will be no more three heading tailgates or new blocks in fresh areas with two headings in the tailgate.			

## 11 INVESTIGATION REPORT SIGN –OFF

The Incident Investigation Team submits this report as a true reflection of the information gathered. To maximize the preventive potential of the investigation report, the findings, conclusions and learning's of the report should be distributed as appropriate.

*Department Manager*



Classification: Personal data

Met Coal\_11-9

## Incident Investigation Report

Version

Date

Name	Signature	Date
<i>[Handwritten Signature]</i>	Confidential	17-03-20
<b>SHE Manager</b>		
Name	Signature	Date
<b>Stephanie Oppermann</b>	Confidential	20/4/2020
<b>General Manager</b>		
Name	Signature	Date
<b>DAMIEN WYNN</b>	Confidential	20/4/20
<b>Head of Operations</b>		
Name	Signature	Date
Glen Britton	Confidential	21/04/2020
<b>Additional EXCO member signoff – if applicable</b>		
Name	Signature	Date


## 12 EVIDENCE &amp; ANALYSIS TOOL APPENDICE

Met Coal\_11-9

## Incident Investigation Report

Version

Date






Met Coal\_11-9

## Incident Investigation Report


Version

Date



## Met Coal\_11-9 Incident Investigation Report


Version  
Date

 AngloAmerican	Anglo Coal (Capcoal Management) Pty Ltd Capcoal Underground Grasshake Operations	Initial Incident Report FRM-GT4LB04
---	---	--

Map / diagram (if required):

Anglo American Plc Risk Matrix		[Copy or paste this matrix into your Excel Workbook. Alternatively, download the template using link]				
Table Types		1	2	3	4	5
Probability (Low, Medium, High)	Impact (Low, Medium, High)	1	2	3	4	5
Low	Low	Low	Low	Low	Low	Low
Low	Medium	Low	Low	Low	Low	Low
Low	High	Low	Low	Low	Low	Low
Medium	Low	Low	Low	Low	Low	Low
Medium	Medium	Low	Low	Low	Low	Low
Medium	High	Low	Low	Low	Low	Low
High	Low	Low	Low	Low	Low	Low
High	Medium	Low	Low	Low	Low	Low
High	High	Low	Low	Low	Low	Low

Print Date	Original Issue Date	Version Number / Date of Issue	Page 4 of 4
5 MAY 2015	5 MAY 2015	R / 1 MAY 2015	

 <b>Anglo American</b>	Anglo Coal (Capeport Management) Pty Ltd Capeport Underground Greenstone Operations		Initial Incident Report FRM GTM.004
	To be completed by reporting person with assistance from Supervisor (Surface Incidents) or ERZC Co-ordinator (UG Incidents)		
ALL Sections of this form are mandatory unless marked.			Incident Number: <b>20172</b>
<b>Title of Hazard / Incident:</b> <b>25-10-19 CH 22-19</b>			
<b>Date occurred:</b> <b>25-10-19</b>		<b>Time:</b> <b>18:00</b>	<b>Yes</b> <input type="checkbox"/> <b>No</b> <input type="checkbox"/>
<b>Date Reported:</b> <b>25-10-19</b>		<b>Time:</b> <b>18:00</b>	<b>Yes</b> <input type="checkbox"/> <b>No</b> <input type="checkbox"/>
<b>Classification:</b> Safety <input checked="" type="checkbox"/> Material Losses / Damage / Business Interruption <input type="checkbox"/> Legal / Regulatory <input checked="" type="checkbox"/> Health Issues <input type="checkbox"/>			
Environment <input type="checkbox"/> Social / Community <input type="checkbox"/> Impact on Reputation <input type="checkbox"/> Workplace Exposure <input type="checkbox"/>			
Department: Longwall <input type="checkbox"/> Development <input type="checkbox"/> Outbye <input type="checkbox"/> Compliance <input type="checkbox"/> Tech Services <input type="checkbox"/> Storage <input type="checkbox"/>			
SHE <input type="checkbox"/> Human Resources <input type="checkbox"/> Commercial / Supply Chain <input type="checkbox"/> Maintenance / Engineering <input type="checkbox"/> Business Improvement <input type="checkbox"/>			
Other <input type="checkbox"/>			
<b>Reportable to external bodies?</b> <b>Yes</b> <input type="checkbox"/> <b>No</b> <input checked="" type="checkbox"/>			
<b>Specific Location:</b> <b>25-10-19 CH 22-19 (Longwall)</b>			
<b>Reported by:</b> <b>John Doe</b>		<b>ID #:</b> <b>123456</b>	
<b>Key Person Involved:</b> <b>John Doe</b>		<b>Contracting Name / Staff:</b>	
<b>Key Person Involved:</b>		<b>ID #:</b>	
<b>Key Person Involved:</b>		<b>Contracting Name / Staff:</b>	
<b>Key Person Involved:</b>		<b>ID #:</b>	
<b>Key Person Involved:</b>		<b>Contracting Name / Staff:</b>	
<b>Injured Person:</b>		<b>ID #:</b>	
<b>Injured Person:</b>		<b>Contracting Name / Staff:</b>	
<b>Others Involved:</b>		<b>ID #:</b>	
<b>Others Involved:</b>		<b>Contracting Name / Staff:</b>	
<b>Initial Investigation Team e.g. ERZC / Crew Supervisor / CSW:</b> <b>George Reid, Andrew Fox</b>			
<b>Equipment Involved:</b> <b>25-10-19 CH 22-19</b>		<b>ERZC Supervisor:</b> include ID # <b>George Reid 25-10-19</b>	
<b>Crew:</b> <b>25-10-19 CH 22-19</b>		<b>Process Area &amp; Department:</b> <b>Longwall</b>	
<b>Shift Length:</b> <b>12</b>		<b>Hours into Shift:</b> <b>8</b>	
<b>Consecutive days worked:</b>		<b>1</b>	
<b>Drugs and Alcohol:</b> <input type="checkbox"/> <b>Yes</b> <input type="checkbox"/> <b>No</b> <input checked="" type="checkbox"/>			
<b>Activity:</b> <b>Longwall cutting</b>			
<b>Incident Description:</b> <b>25-10-19 CH 22-19</b>			
<b>Immediate Direct Cause:</b> <b>25-10-19 CH 22-19</b>			
<b>Immediate Corrective Actions Taken:</b> <b>25-10-19 CH 22-19</b>			
<b>Refer to AAMC Risk Matrix to determine the appropriate Consequences (see matrix on back page)</b>			
<b>Consequence Type:</b> Safety Injury <input type="checkbox"/> Material Losses / Equipment Damage / Business Interruption <input type="checkbox"/> Legal / Regulatory <input type="checkbox"/> Environment <input type="checkbox"/> Hazard Potential / Consequence matrix used <input type="checkbox"/>			
<b>Actual Consequence:</b> <b>Insignificant</b>		<b>Minor</b> <input type="checkbox"/>	
<b>Not Applicable for Hazards</b>		<b>Moderate</b> <input type="checkbox"/>	
<b>High</b> <input type="checkbox"/>		<b>Major</b> <input type="checkbox"/>	
<b>Potential Consequence:</b> <b>Insignificant</b>		<b>Minor</b> <input type="checkbox"/>	
<b>Moderate</b> <input type="checkbox"/>		<b>High</b> <input type="checkbox"/>	
<b>Major</b> <input type="checkbox"/>		<b>Very Major</b> <input type="checkbox"/>	

 <b>AngloAmerican</b> <small>A subsidiary of Anglo Platinum Limited</small>	<b>Angle Coal (Capex) Management Pty Ltd</b> Capex Underground Gossames Operations	<b>Incident Report Form GTM-054</b>
Was this hazard, defect or incident being effectively controlled on shift?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If not, why not?		
Safety:		
Persons Injured / Lost time:		Medical Treatment: YES <input type="checkbox"/> NO <input type="checkbox"/>
		Hospitalised: YES <input type="checkbox"/> NO <input type="checkbox"/>
Environmental Media Impacted:		Environmental Impact:
Hazard:		
Hazard Agent:		Hazard Type: Act <input type="checkbox"/> Condition <input type="checkbox"/>

Timeline:	
01/01/18 08:00	Example: Attended Start of Shift
<b>Before the Incident</b>	
Incident Occurred	
<b>After the Incident</b>	


Addtional Actions to prevent recurrence: (SRX Controller Supervisor to complete)

Initial Incident Report Checklist:

Contact relevant site personnel: Completed <input checked="" type="checkbox"/>	Have statements been collected?: Completed <input type="checkbox"/> <i>e.g. Key person involved, witnesses (submit with this form)</i>
Collect any relevant SRHE MS Documents: Completed <input type="checkbox"/>	Take photos of incident scene as required: Completed <input type="checkbox"/>

Print Date: 19/02/19 12:32 PM	Original Issue Date: 3 JULY 2012	Version number / Date of Issue: 0 / 1 MAY 2019	Page 2 of 4
----------------------------------	-------------------------------------	---	-------------

 <b>Anglo American</b>	<b>Anglo Coal (Capital Management) Pty Ltd</b> Capital Underground Coalmine Operations	<b>Initial Incident Report</b> FPM GTM.004
<b>Task Description</b>	<b>By Whom</b>	<b>Action Due (date)</b>
<p>Is counselling of the CMW required (see text to be sent to HR)?</p> <p>Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>CMW to be counselled in line with the Anglo Coal Consequence Model and Applicable Misconduct Policy. Evidence to be sent to HR for file.</p>	DB	25/11/17
<b>Person Reporting</b>	<b>Name:</b>	<b>Signature:</b>
Signature: [Redacted]	Signature: [Redacted]	Signature: [Redacted]
<b>Date:</b>	<b>Date:</b>	<b>Date:</b>
25/11/17	25/11/17	25/11/17
<b>Verification Sign Off:</b>	<b>Name:</b>	<b>Signature:</b>
Undermanager/ LHO	Name: [Redacted]	Signature: [Redacted]
Superintendent Manager	Name: [Redacted]	Signature: [Redacted]
Entered Into Enrolment By:	Name:	Signature:
<p>If reported to the DFMME, is a form SA required?</p> <p>Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>If Yes, Raise relevant task for the completion of Form SA</p>	<p>Is a 'Learning From Incident' Investigation Required?</p> <p>Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>If Yes, Raise relevant task for the completion of LFI report</p>	
<b>LFI Task Enrolment ID:</b>	<b>Completion Date of Task:</b>	
<b>Print Date</b>	<b>Original Issue Date</b>	<b>Version number / Date of Issue</b>
25/11/17	25/11/17	25/11/17
<b>Page 3 of 4</b>		

Met Coal_11-9	Incident Investigation Report	Version Date
---------------	-------------------------------	-----------------

Time Series Event Chart

- # 1 - TM.00028038 25/10/19 18:05:00  
Shearer latched due to >1.9% CH4 at TG roadway
- # 2 - TM.00028039 25/10/19 18:25:00  
Carried out inspection at Tg while shearer was down
- # 3 - TM.00028040 25/10/19 18:35:00  
Detected >2.5% CH4 (2.56%) at Tg betweenface & 19ct
- # 4 - TM.00028041 25/10/19 18:50:00  
Reported to MSO
- # 5 - TM.00028042 25/10/19 18:50:00  
Waited for further instruction

Met Coal\_11-9

## Incident Investigation Report

Version

Date

**Unwanted Event:****808TG gas exceedance  
(> 2.5% CH<sub>4</sub>)****Why?**LW TG gas sensor was only  
reading 1.9%**Why?**LW TG gas sensor was  
located in the C hdg return  
which was diluted**Why?**Methane did not travel  
inbye the face through the  
inbye cut through as  
designed**Why?**2 psi stopping was still in  
place at 20ct inbye the LW  
face



**Met Coal\_11-9****Incident Investigation Report****Version****Date**

## 13 RECORD OF AMENDMENTS

Issue 6	:	Full review to align the investigation report to the Learning from Incidents process being rolled out at Met Coal in 2018.	08 June 2018, Chris Gately, Lynda Butler
Issue 5	:	<ul style="list-style-type: none"> <li>• Sign off table updated to include "Additional EXCO" member signoff.</li> <li>• Section 7 – New – Critical Control Failure (for HPI's only)</li> <li>• References to Met Coal removed.</li> </ul>	15 September 2015, Allan Gordon
Issue 4	:	Reviewed Sign off table updated to include sign off from Head of Operations	22 April 2014, Allan Gordon
Issue 3	:	Reviewed for currency – reformatted	8 January 2014, Bruce Gavin
Issue 2	:	Reviewed to align with Enablon Incident Database	6 March 2013, Graeme Redding
Issue 1	:	New Template	15 December 2011, Bruce Gavin

