



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

20.1.12. Appendix 11: ERT Debrief Form

Debrief Officer: NEAL BARNES Role: U/MANAGER Date/Time of Debrief: 6/5/20 1604 HRS

Date of Emergency: <u>6-5-20</u>	Time Emergency Started: <u>1500 HRS</u>	Time Emergency Finished:
Type of Emergency: <u>IGNITION</u>		
Location of Emergency: <u>LW TO</u>		
Name: <u>ADAM MAGGS</u>		
Crew/Department: <u>A LABORER</u>		
Work location: <u>TG</u>		
Role in ERT: <u>DEBRIEF</u>		
Time Notified of Emergency:		
How Notified:		
Time Your Response Started:		
No. of responders in ERT:		
Breakdown of Emergency		
Time	Description	
1425	<p>Surgeon started approx 120ft. Went to Double Check 125-138 AS it was unsatisfactory. Maggs left to go to M6 to let coshew know face conditions AND THAT WE DON'T HAVE TO RAMP.</p> <p>HUNG UP PHONE AND FELT PERCUSSION. AT THIS STAGE THOUGHT WE HAD LOST 36 ft. 15 SEC AFTER FIRST PERCUSSION FELT 2nd PERCUSSION. AT THIS STAGE MADE MY WAY TO TG. HEARD ON THE OAC "WHERE NO GOOD DOWN THERE". CONTINUED TO WALK TO TG WITH BEAU LAD & MAGGS. THEN CAME ACROSS Injured coal mine workers 5, 3 and 4 THEY SAID WHERE BURNT. SAW 2 MORE LIGHTS COMING DOWN FACE. BEAU AND MAGGS ATTEMPTED TO Injured coal mine workers 5, 3 and 4 MAGGS WENT TO TG AND SAW Injured coal mine worker 1 at</p>	

M.D.FACE. THIN ~~SEED~~ Injured coal mine worker 2 ~~STUMBLED~~.
 ARRIVED TO HIM. GOT EVERYONE TO VEHICLES.
 AND TRANSFERRED TO SURFACE.

FACE CONDITIONS.

FAULT. 112-113. 2.8-3m. POWD THROW.

142 ± 1m UP THROW.

143 ± 600m UP THROW.

143½ 400m DOWN THROW.

CAVITY 144-149. ABOVE 3m.

TIL TO FACE GOOD. FACE STANDING UP.

HAD BEEN WORKING ON GETTING 145 & 146 TIPS UP.

GAS AT T6. GB. 0.6% CH₄. LITTLE BIT IN
 ROAD WAYWAY M.D.FACE. 1.4%.

T6 CONDITIONS: HEAVY ROCK. GOOD RIGHT UP THE
 BACK OF 149. CAVITY DID NOT PROTRUDE INTO ROADWAY.

ALOT OF ROCK COMING FROM HIGH ABOVE.



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

Assessment of Response -	
Topic	Comments
Notification of Emergency	
Activation of ERT	
Resources available (equipment and personnel)	
Equipment condition	
Communication during response	
Information provided during response	
Additional support provided	
Adequate skills/training to respond	
Other	

Critical Issues	Recommended Corrective Actions	By Whom

GRO-208-PRO-Mine Emergency Response System	Original Issue Date: 06/09/2013	Version:	9	Printed: 6/05/2020 Page 48 of 86
		Date of Issue:	12/11/2019	
PRINTED COPIES OF THIS DOCUMENT ARE UNCONTROLLED AND DEEMED VALID ONLY ON THE DAY OF PRINTING				



GROSVENOR COAL MINE
PRO-Mine Emergency Response System

Employee Assistance Scheme provided/offered to ERT Member

YES NO

Details:

ERT Member Signature:

Copy sent to Manager for review & actioning (circle): YES/NO	Additional information attached (circle): YES/NO Details:	Enablon Incident No:
Debriefing Officer Signature:		

(COPY TO MATT KENNEDY

WALTER ALLEN

6/5/20 7:20 PM