

Tasks

Scope

Entity Moranbah North
 Action Plan Action Plan for >2.5% methane at TG drive and in LW604 TG roadway
 Action Plan ID AP.00742773

Archives

Archived ✘

Task Details

Task ID TS.01096536
 Task Name Revise the UIS strategy in similar areas to ensure adequate drainage of the GML
 Task Description Revise the UIS strategy in similar areas to ensure adequate drainage of the GML
 Department Responsible Mining Operations
 Task Type Data Review / Verification
 Priority Low
 Hierarchy of Controls Administration
 What happened (Agency)

Task Status

Start Date 24/07/19
 Original Due Date 15/09/19
 Revised Due Date
 Real Due Date 15/09/19
 Status Completed
 Progress 100%
 No. of revision (due date) 0

Frequency of reoccurrence None

Team

Person Responsible Doyle Kevin - 16379_Mc

Completion

Completion Date 05/09/19
 Completion Comments All UIS boreholes in area of GML within 2-4m of GM are designed to conduct floor hits at regular intervals to assist in draining GML
 Is follow up required? No

What needs to be done

Historic Documentation
 Related Files
 Comments





Created by **Khanthamala Nakhalath {Contributor}** on **29/08/19 12:24:00**

Last modified by **Kevin Doyle {Contributor}** on **05/09/19 07:37:20**
