



**Queensland
Government**

Mackay Office

P.O. Box 1801, Mackay, QLD 4740

Phone: 07 4999 8512, Fax: 07 49998519

Mine Name	MineID	Operator	Activity Type	Activity Date
Grasstree Mine	MI01459	Anglo Coal (Capcoal Management) Pty Ltd	Postal Mine Record Entry	02/01/2020

Vision: Our Industries Free of Safety and Health Incidents

Mine Record Entry

This report forms part of the Mine Record under s68 of the Coal Mining Safety and Health Act 1999. It must be placed in the Mine Record and displayed on Safety Notice Boards.

Note that inspection or audit activities conducted by the Mines Inspectorate are based upon sample techniques. It remains the primary responsibility of Mine Personnel to identify hazards, and risks associated with Operations and ensure those risks are at an acceptable level.

Today 2 January 2020, I contacted SSE Damien Wynn by telephone to verbally advise him he has met the directive given to him by Inspector Brennan 24 December 2019.

By meeting the directive the Grasstree Mine can resume production in the 909 - 910 face roadway single entry panel.

The SSE has provided inspectors with a number of documents and responses to meet his obligation in achieving an acceptable level of risk for the single entry development panel.

Paul Brown

Inspector of Mines